

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 03/03/2012	3. Time Prepared 1730
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Leutke, Planning Section Chief		6. Operational Period 0700, 03/01/2012 – 0700, 03/08/2012
7. Personnel Roster Assigned				
Name		ICS Position		Contact Phone
Matthew Haak		Situation Unit		[REDACTED]
8. Activity Log				
Time	Major Events			
0900	Observations: <ul style="list-style-type: none"> Observed additional scrape work near Confluence of Talmadge Creek and Kalamazoo River. Observed continued Talmadge Creek restoration work near MP1.85. Observed continued excavation work on Talmadge Creek near A Drive. Observed site prep for excavation work on Talmadge Creek near A Drive. .Observed pumparound system being modified on Talmadge Creek near A Drive. Observed elevated river levels at Confluence. Observed bypass discharge system at Confluence. 			
1500	Return to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				